

User Guide

MC Cable
GaylordBox
LABOR SAVING • SEQUENTIAL FOOTAGE

The Gaylord Box arrives on a pallet, making it easy to move into position with a forklift.

Step 1

Remove the lid.

Step 2

Depending on your pulling setup, you may choose to remove the center cardboard triangle by pulling it straight up.

Step 3

Lift the first loop of Cerrowire MC Cable to load into your equipment. The MC Cable pays out from the Gaylord in the correct direction for smooth installation.

Step 4

Colored chevrons printed on the armor show the conductor colors inside and **point in the easiest direction to pull**. There's also a black line every two feet, making it **easy to cut exact lengths** without using a tape measure.

MC Cable Gaylord Box Specs

AWG/ conductors	Footage	Approx. Net Product WT Lbs.
12/2 solid	6000	620
12/2 stranded	6000	633
12/3 solid	5000	670
12/3 stranded	5000	698



For more information scan the QR code to learn more.



For your safety we recommend wearing safety glasses and protective gloves.



by cerrowire®

Electrical Distribution 800.523.3869

©2026 Cerrowire Rev 02/2026
A Marmon/Berkshire Hathaway Company